LT - NOTE ARE ME PEDERAL COMMUNICATIONS COMMISSION FILE 1220 FE-788 Field Engineering Bureau FILET Washington, D. C. 20555 Project XI-18 May 17, 1967 TO ENGINEERS IN CHARGE (FOD) Project Title: New Code Reyers for Examination Use Subject: Improvements to Atko Mini-Reyer Case Latch The Engineer in Charge, Buffalo has furnished information which describes the methods he has utilized to improve the latch and certain mounting screws for this instrument. His report is as follows: "We experienced difficulty with the cases of both of the ATKO MINI-KEYER units at this office in that they easily popped open, especially when placed with the carrying handle up. We have corrected the problem with two minor modifications. The cases now stay closed under normal handling. "The first modification was to reshape the case latching catch hook with a fine tool-maker's file. It was noted that the original latching surface of the catch hook was tapered so that the catch would easily slide open. By reshaping the hook as shown in the sketch below, the latch holds securely. "The second modification was to replace the two screws holding the power cord storage bracket. We found that a twisting motion on the case cover causing the case to pop open was the result of the protruding heads on the screws used to bold the power cord bracket on the case end. We replaced the binder head screws with 1/4" x 6-32 FLAT HRAD machine screws. We countersunk the screw heads into the case by drilling the case with a 5/16" drill. The screw heads are flush with the case surface. "This office has a supply of finished 1/4" x 6-32 flat head screws and can send them to any office requesting them." Courtesy of the N7CFO archives. WWW.N7CFO.COM FEDERAL COMMUNICATIONS COMMISSION MAY 22 1987 PORTLAND, OREGON

Original shape of latching book surface tending to slide open.



Modified shape of hook latching surface holds without sliding open.



J. Patrick Scanlon Chief, Field Offices Division